

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease							
Proposed Slipline Repairs - From 2007 & 2008 Reports											
SUBDIVISION	ADDRESS	DISTANCE CLEANED & TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Broadview	7766 Meadow	255	15-214		15-170	Tap, left, clean Aband tap, left Aband tap, right Tap, top, clean Aband tap, left Tap, right, clean Aband tap, right Tap, right, clean Roots in joint, med Roots in joint, med Roots in joint, med Roots in joint, med Tap, left, clean very slight offset jnt	47.4 66.4 73.5 88.5 155.3 160.1 163.1 172.8 193.4 198.1 210.1 225.1 248.1 254.7	03/19/2007	Rootx/Slipline		
Broadview B	7922 Meadow/Emer (in yd of 7933 Ridgemont)  7933 Ridgemont/Emer  7944 Meadow Lane	451	15-212		15-211	Protr tap, hammer, R Hammer tap, left  RIJ, med Aban tap, Left Aban tap, Right RIJ, hvy Belly ends RIJ, hvy Aband Tap, right Aband tap, left offset joint RIJ, damaged joint Hammer tap, left Grease in jnt, hvy, crack RIJ, med RIJ, hvy Tap, right, roots	22.4 36.4  40.6 57.2 59.2 67.5 91.0 116.0 193.0 195.0 202.5 222.2 224.5 289.2 294.1 295.5 296.5	08/23/2007	Repair tap (Emergency) Repair tap (Emergency)  Point repair (Emergency)  Repair tap  Slipline Incomplete run/Re-TV		
Broadview B	8000 Meadow Ln	0	15-211		15-212	Tap, right, separated Aband tap, left RIJ, hvy Tap, right, roots/hvy	75.9 77.8 148.0 154.3	08/24/2007	Slipline (Same as above but entered opposite direction)		

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease							
Proposed Slipline Repairs - From 2007 & 2008 Reports											
SUBDIVISION	ADDRESS	DISTANCE CLEANED & TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Broadview II	7999 Meadow Ln	388	15-183		15-182	Tap, right, roots lgt Root in joint, lgt Aband tap, left Roots in joint, med Tap, right, roots lgt Roots in joint, lgt Belly starts/1/2" pipe Belly ends Roots in joint, lgt Belly starts Belly ends Roots in joint, lgt Roots in joint, lgt Tap, top, clean Tap, left, clean Roots in joint, lgt Tap, left, clean Tap, top, clean Tap, left, clean MH 15-182	26.5 57.0 84.0 85.3 91.1 92.5 115.3 124.6 129.0 134.0 147.9 159.0 166.0 218.9 257.6 293.1 313.4 331.0 367.2 387.8	05/18/2007	Possible main line repl. Possible slipline also		
Green Spring Valley	8288 Chestnut Bid as 8255 N Larch	93	11-261		11-263 or Dead end	Roots in joint, med Aband. Tap, roots lgt Roots in joint, light Tap, right, clean (rep) Tap, left, clean Dead end/11-263	4.0 15.5 15.7 51.9 86.4 93.0	03/30/2007	Rootx/slipline		
Green Spring Valley	8122 Burch	536	11-257		11-256	Tap, left, roots/hvy Aband tap, left Tap, left Tap, left, clean Ab tap, left, roots/hvy Tap, left, clean Ab tap, left Ab tap, left RJ, hvy RJ, lgt RJ, hvy AB tap, left Tap, top, clean MH 11-256	39.9 134.4 142.0 216.0 224.8 289.3 301.2 388.8 401.2 449.1 488.1 495.0 498.8 535.7	08/31/2007	Repair Tap (Same repair as shown 8/28/07)  Slipline complete line		Also see 8/28/07 - 2 incomplete runs

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease							
Proposed Slipline Repairs - From 2007 & 2008 Reports											
SUBDIVISION	ADDRESS	DISTANCE CLEANED & TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Heritage Hills	6511 Heritage Dr	318	21-52		21-53	Roots Joint, Med Roots Joint, Med Tap, right, clean Roots Joint, Med Tap, right, clean MH 21-52	47.6 60.3 63.1 241.1 258.4 317.8	01/02/2007	Rootx/Slipline		
Heritage	6511 Martin Rd	0	21-53		21-52	Roots in joint, lgt Roots in joint, lgt Roots in joint, lgt Tap, left, roots/lgt Tap, right, clean Roots in joint, lgt Roots in joint, lgt Roots in joint, lgt Roots in joint, lgt Roots in joint, lgt Tap, right, clean Tap, top, clean MH 21-52	35.4 56.1 62.1 63.1 64.1 98.2 190.1 215.3 225.7 230.4 261.7 278.4 319.8	06/14/2007	Rootx & Slipline	Already entered 1/2/07 & 1/5/07	
Springvale	6699 Valley Rd	221	20-164		20-163	Tap, right Roots in joint, lgt Roots in joint, med Roots in joint, lgt Aband tap, right Tap, top Tap, top Aband tap, right MH 20-163	3.1 3.5 6.6 12.0 86.9 100.6 149.4 173.9 220.6	04/30/2007	Rootx/slipline		
Town	380 E SR 662	0	9-110		9-129	Tap, top, clean Roots in joint, hvy Roots in joint, med Roots in joint, med Roots in joint, med Roots in joint, med Tap, left, clean Tap, left, clean Protruding tap	4.0 13.8 23.6 34.2 59.8 119.8 126.2 221.1 230.1	01/16/2007	Rootx/Slipline  Repair Tap		
Town	Hillcrest & Treelane	445	10-101		C.O.	Numerous RIJ places	72-361	12/19/2007	Slipline		

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease							
Proposed Slipline Repairs - From 2007 & 2008 Reports											
SUBDIVISION	ADDRESS	DISTANCE CLEANED & TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Twin Oaks	7399 Lenn Rd	232	15-132		15-133	Roots in joint, light Roots in joint, light Roots in joint, light Tap, left, clean (rep) Aband tap, right Roots in joint, med Tap, right, clean (rep) Tap, right, clean (rep) Tap, left, clean Tap, left, Protruding	7.6 13.3 21.0 35.5 48.4 52.1 71.4 124.8 144.9 194.9	02/21/2007	Rootx/Slipline  Repair tap		
Broadview B	8000 Ridgemont Dr	269	15-210		Go West	Tap, right, clean Tap, right, clean Aband tap, right Roots in joint, lgt Tap, right, clean Aban tap, right, root/lgt Roots in joint, med Roots in joint, lgt Aban tap, right, root/lgt Tap, straight, clean	39.0 126.1 133.7 179.9 196.7 221.0 226.0 261.1 268.5 268.6	05/22/2007	Rootx & Slipline		
Concord Green	Hwy 261	218	15-49		15-47	Tap, right, clean Tap, left, clean Roots in joint, lgt Tap, right, clean Roots in joint, lgt Aband tap, right, clean Roots in joint, lgt Roots in joint, lgt Tap, right, clean Roots in joint, lgt Roots in joint, lgt MH 15-47	3.8 17.3 53.6 69.4 78.3 84.4 111.0 161.0 168.1 189.1 198.6 218.1	05/23/2007	Rootx & Slipline		
Forest Park	612 Forest Park Dr	0	13-180		C.O.	Tap, right, clean Roots in joint, lgt Roots in joint, lgt Tap, right, clean Roots in joint, lgt Tap, top, clean Tap, left, clean Cleanout	36.5 121.4 133.8 157.5 171.7 205.3 207.2 210.6	05/24/2007	Rootx & Slipline		

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease							
Proposed Slipline Repairs - From 2007 & 2008 Reports											
SUBDIVISION	ADDRESS	DISTANCE CLEANED & TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Green Spring Valley	8455 Sycamore	185	11-209		11-197	Roots in joint, lgt Roots in joint, med Roots in joint, med Roots in joint, lgt Main line repaired Tap, left MH 11-197	66.8 81.4 86.5 100.8 124.5 124.5 184.9	06/01/2007	Rootx & Slipline		
Green Spring Valley	8200 Chestnut	76	11-333 New MH		11-264	Roots in joint, lgt Tap, left Roots in joint, lgt Roots in joint, hvv	47.7 51.6 56.0 58.9 64.5 67.3 71.5 76.3	06/06/2007	Rootx & Slipline		
Green Spring Valley	4444 E Birch Dr	358	15-209		15-55	Repair in main begins Tap, right, clean Pipe repair ends Roots in joint, lgt Tap, top, clean Roots in joint, med Roots in joint, med Roots in joint, lgt Roots in joint, lgt Roots in joint, lgt Roots in joint, lgt Roots in joint, med Aband tap, right, clean MH 15-55	136.1 143.2 147.4 176.9 204.3 216.6 224.2 228.7 239.2 244.3 258.5 305.8 357.9	06/06/2007	Rootx & Slipline		
Heritage Hills	6555 Yorktown	180	21-51		21-50	Offset jnt, severe Tap, right, OK Tap, top, OK Plastic to Clay RIJ, med Tap, hammer, bad RIJ, med RIJ, med RIJ, lgt RIJ, lgt RIJ, med RIJ, lgt Prot Tap, roots	9.7 18.2 69.3 95.6 108.2 109.6 110.1 125.7 130.8 140.4 155.9 162.3 180.1	10/03/2007	Point Repair  Repair Tap  Slipline  Repair Tap		Also see 6/13/07
Heritage	6599 Yorktown	0	21-50		21-51	Roots in joint, med Roots in joint, lgt	2.0 5.9	06/13/2007	Rootx & Slipline		Also see 10/3/07







